



Basic Gearing Ratio Chart

				R	E	A	R		
		36	37	38	39	40	41	42	43
F	16	2.25	2.31	2.37	2.43	2.50	2.56	2.62	2.68
R	15	2.40	2.46	2.53	2.60	2.66	2.73	2.80	2.86
O	14	2.57	2.64	2.71	2.78	2.85	2.92	3.00	3.07
N	13	2.76	2.84	2.92	3.00	3.07	3.15	3.23	3.30
T	12	3.00	3.08	3.16	3.25	3.33	3.41	3.50	3.58
	11	3.27	3.36	3.45	3.54	3.63	3.72	3.81	3.90